

Windshield Lower

Description

Impact damage to the windshield lower area may spread to the back of the panel and wiper mounting area, calling for replacement of the affected skins.

Mass Production Body Welding Diagram

